ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

1.General Details

Zone No:Dasarahalli Ward No:14 Ward Name:Bagalakunte

Street ID: W0307,W0276,W0311,W0288,W0276,W0475,W0476,W0466,W0593 Street Name:

Significant Landmark: Soap Factory Layout

Segment_No: 14/S-W0475/S8548 Total_Length: 404.91

Segment Details

Seg No.	Length(mts)	Start Coordinates	End Coordinates	From Landmark	To Landmark	Work Type	Other Work
1	239.34	13.06865216 6934417-77.49470740 556718	13.05797543 911286-77.49680489 301683	Byraveshwara Circle	Dead end	Asphalting	Asphalt
2	34	13.06892390 268085-77.49701946 973802	13.05885466 2350766-77.49732524 156572	Byraveshwara Nagara	2nd cross	Asphalting	Asphalt
4	34.59	13.05772591 159117-77.49691620 469093	13.05752341 5249547-77.49686390 161516	Burrial Ground	SWD Drain	Asphalting	Drain
3	96.98	13.06556205 4802892-77.49285936 355592	13.05474593 2546848-77.49260455 369951	Soap factory Layout	Dead end	Others	Drain

2.Work Details

History of Road / Lane / Circles

Name of the Work:Desilting and Resetting of drains and re Asphalting to soap factory Layout in Bagalagunte Ward no 14

Sanctioned Amount: 5000000 Sanctioned Year: 2022-23 Year: 2022-23

AE/Ward.14

Tender: Tender
CE/DZ/TS/73/21-22, Dt.14.01.2022

Work Details: EE/DD/AS/85/21-22, Dt.13.01.2022
Job No/Work Code:014-18-000061

Work Order No: EE/DD/WO/75/22-23

Work Order Date: 01/07/2022

Period of Extention: 5

Defect Liability Period From: 06/03/2023

Defect Liability Period To: 05/03/2024

3.Contractor Details

Zone: Dasarahalli

Ward No: 14

Ward Name: Bagalakunte

Street ID: W0475

Name of Contractor: NMShivakumar

Contractor Reg No (BBMP/PWD): 12932

4.Field Inspection Details

Category	Image
Desilting and Resetting of drains and re Asphalting to soap factory Layout in Bagalagunte Ward no 14	

Remarks

Sl.No	Stage_No	Designation	Remarks	StageName	Action
1	1	AE	Road Work History Added	Data Uploading	Initated
2	2	AEE	Approved	Review Application	Approved
3	3	EE	Approved	Review Application	Approved
4	4	SE	inspected the drain length and road	Review Application	Approved
5	5	CE	APPROVED	Final Approval	Approved